



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	1	Kempegowda Ward
Street ID	Street Name	Significant Landmark
W0466	1st Main Rd	Yelahanka old Post office Road Opposite to Rajakum
Segment No.	Total Length (m)	
1/S-W0466/S110814	86.72	

Segment Details

Seg No.	Length (m)	Start Coordinates	End Coordinates	From	To
1	86.72	77.596977 13.099971	77.597759 13.099804	W0357	W0359

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of CC Road at Yelahanka old Post office Road Opposite to Rajakumar house Road and and Drain at Cross roads of Yelahanka oldtown in ward n	1500000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	Work Details	Job No. / Work Code
Tender	Construction of CC Road at Yelahanka old Post office Road Opposite to Rajakumar house Road and and Drain at Cross roads of Yelahanka oldtown in ward no 01 Yelahanka Sub- Division Yelahanka zone	001-15-000014
Work Order No.	Work Order Date	Period of Extention
EE(YNK.DYE-PMT- 4/WO/56/2014-15	28/01/2015	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
28/01/2015	27/01/2016	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
SRINIVAS B M		0.00
Phone No.	E-Mail ID	

Zone: YELAHANKA

Ward No: 1

Ward Name: Kempegowda Ward

Street ID: W0466

Date: 03/12/2016

Time: 13:40:10

RH20161203134010

Page 1 of 3

Field Inspection Details

Number of Trees

Any Other Information

Name

0

CHANDRASHEKAR

Date of Inspection

Remarks

03/12/2016

COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA

Ward No: 1

Ward Name: Kempegowda Ward

Street ID: W0466

Date: 03/12/2016

Time: 13.40.10

RH 20161203134010

Page 2 of 3

Road Condition



This photo seems out of range.

Road Condition



This photo seems out of range.

Road Condition



This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	03/12/2016	02/01/2017	COMPLETED
SE	VASU K M	03/12/2016	02/01/2017	COMPLETED
EE	SRINIVAS	03/12/2016	02/01/2017	COMPLETED
AEE	G.B. PRABHAKAR	03/12/2016	02/01/2017	COMPLETED
AE	CHANDRASHEKAR	03/12/2016	02/01/2017	COMPLETED
AE	CHANDRASHEKAR	03/12/2016	02/01/2017	COMPLETED